



152512050049

正本

检测报告

TEST REPORT

报告编号

YNZKBG20220304004-2

Report No

项目名称

大理丰顺医疗废物处置有限公司 2022 年 2 月份暨第一季度自行监测

Name

委托单位

大理丰顺医疗废物处置有限公司

Client

项目地址

大理州大理市下关镇吊草村大风坝垃圾处理场以西

Address

样品类别

土壤

Type

编制:

Compiled by

审核:

Inspected by

签发:

Approved by

签发日期:

Approved Date



2022 年 03 月 04 日

Y M D

云南中科检测技术有限公司

Yunnan Sino-sci Testing Tech. Co, LTD

报告日期

2022 年 03 月 04 日

Report Date

Y M D

申明

Introduction

1.报告无“CMA 资质认定章”和检测单位“检测专用章”及“骑缝章”无效。

This report no seal on the perforation and CMA qualification certification seal and special seal for testing is invalid.

2.报告无编制人、审核人、签发人签名无效，报告经涂改无效。

This report without prepare people signature, audit staff signature, approver signature is invalid, The report by alter is invalid.

3.报告未经本机构批准，不得复制（全文复制除外）本报告或证书。

This report or certificate can't be copied (except in full) without the approval of the agency .

4.对委托人送检的样品进行检测的，检测报告对样品所检项目的符合性情况负责，送样样品的代表性和真实性由委托人负责；除委托方特别声明并支付样品管理费以外，所有样品超过标准或技术规范要求的时效性均不再留样。

If the sample submitted by the client is tested, the test report shall be responsible for the conformity of the items tested by the sample, and the client shall be responsible for the representativeness and authenticity of the sample submitted; Unless the entrusting party makes a special statement and pays the sample management fee, the timeliness of all samples exceeding the requirements of standards or technical specifications will not be retained.

5.报告未经检测单位同意不得用于广告，商品宣传等商业行为。

This report without the consent of the testing organization shall not be used for advertising, advertising products such as business practices.

6.委托方如对本检测报告有任何异议，请于收到报告之日起十五日内向本公司提出申请，逾期不申请的，视为认可本检测报告。

If the client has any objection to the test report, please apply to the company within 15 days from the date of receiving the report. If the client fails to apply within the time limit, it shall be deemed to have approved the test report.

地 址： 云南省昆明经济技术开发区云大西路 39 号新兴产业孵化区 3 幢 3 层厂房
Address: The 3-story factory Building, 3 Building, Emerging Industry Incubation Zone, No.39 Yunda West Road, Kunming Economic and Technological Development Zone, Yunnan Province.

邮 编： 650500

Postcode ID:

电 话： 0871-63852008

Telephone No:

传 真： 0871-63802005

Fax No:

网 址： www.sttynzk.com

Website:

1.检测信息

表 1 检测信息

客户基本情况										
委托单位信息	单位名称	大理丰顺医疗废物处置有限公司								
	通讯地址	大理州大理市下关镇品草村大风坝垃圾处理场以西								
	联系人	姚燮林	联系电话		13987202591					
受检单位信息	单位名称	大理丰顺医疗废物处置有限公司								
	通讯地址	大理州大理市下关镇品草村大风坝垃圾处理场以西								
	联系人	姚燮林	联系电话		13987202591					
样品基本情况										
样品类别	样品名称	采样点位	采样频次		采样人员	采样时间	收样人员	收样时间	分析时间	样品状态描述
			天数	次/天						
土壤	土壤	S1: 厂界东侧 (E100°16'5.39", N25°31'31.97")	1	1	熊瑞 李雄磊	2022.02.11	吕梦林	2022.02.12	2022.02.12- 2022.02.22	样品为黄棕色、湿、 少量根系、轻壤土。
		S2: 厂界南侧 (E100°16'2.48", N25°31'30.79")								样品为黄棕色、湿、 少量根系、轻壤土。
		S3: 厂界西侧 (E100°16'2.42", N25°31'32.18")								样品为红棕色、湿、 无根系、中壤土。
		S4: 厂界北侧 (E100°16'4.10", N25°31'32.96")								样品为黄棕色、潮、 无根系、砂壤土。



2.生产工单编号、检测类别、项目、方法、设备

表 2 检测分析方法及主要仪器设备一览表

生产工单编号	样品类别	检测项目	检测方法	检测和分析设备	仪器编号	分析人员	最低检出限
YNZKSC 20220208043	土壤	pH	HJ 962-2018 土壤 pH 的测定 电位法	PHS-3C 型 pH 计	STT-FX091	杨传健	0.01pH 单位
		汞	GB/T 22105.1-2008 土壤质量 总汞、总砷、总铅的测定 第 1 部分：土壤中总汞的测定 原子荧光法	AFS-8520 双道原子荧光分光光度计	STT-FX084	郭习林	0.002mg/kg
		砷	GB/T 22105.2-2008 土壤质量 总汞、总砷、总铅的测定 第 2 部分：土壤中总砷的测定 原子荧光法	AFS-8520 双道原子荧光分光光度计	STT-FX084		0.01mg/kg
		铜	HJ 491-2019 土壤和沉积物铜、锌、铅、镉、铬的测定 火焰原子吸收分光光度法	AA-7003 原子吸收分光光度计	STT-FX008		1mg/kg
		锌					1mg/kg
		铅					10mg/kg
		镍					3mg/kg
		镉	HJ 803-2016 土壤和沉积物 12 种金属元素的测定 王水提取-电感耦合等离子体质谱法	ICAP RQ ICP-MS	STT-FX149		0.07mg/kg
		六价铬	HJ 1082-2019 土壤和沉积物六价铬的测定 碱溶液提取-火焰原子吸收分光光度法	AA-7003 原子吸收分光光度计	STT-FX008		0.5mg/kg

3.检测结果

表 3 土壤检测结果表

检测点位 采样时间 /样品编号	2022.02.21			
	S1: 厂界东侧	S2: 厂界南侧	S3: 厂界西侧	S4: 厂界北侧
检测项目 (单位)	YNZKSC20220208043-S001	YNZKSC20220208043-S002	YNZKSC20220208043-S003	YNZKSC20220208043-S004
pH (无量纲)	6.65	7.01	7.03	6.96
砷 (mg/kg)	13.1	44.5	23.4	11.9
汞 (mg/kg)	0.085	0.061	0.113	0.322
镉 (mg/kg)	0.12	0.33	0.15	0.29
六价铬 (mg/kg)	未检出	未检出	未检出	未检出
铜 (mg/kg)	17	47	13	24
铅 (mg/kg)	35	152	35	23
锌 (mg/kg)	141	168	109	92
镍 (mg/kg)	19	62	35	15
备注	采样方法依据: HJ/T 166-2004 土壤环境监测技术规范。			

** 报告结束 **



附图:

大理丰顺医疗废物处置有限公司 2022 年 2 月份暨第一季度自行监测点位图

