



检测报告

TEST REPORT

152512050049

报告编号

YNZKBG20240925007-3

Report No

项目名称

大理丰顺医疗废物处置有限公司 2024 年 9 月地下水自行监测

Name

委托单位

大理丰顺医疗废物处置有限公司

Client

项目地址

大理州大理市下关镇吊草村大风坝垃圾处理场以西

Address

样品类别

水和废水

Type

编制:

Compiled by

校核:

Proofread check

审核:

Inspected by

签发:

Approved by

签发日期:

2024 年 09 月 25 日

Approved Date

Y M D

云南中科检测技术有限公司

Yunnan Sino-sci Testing Tech. Co, LTD

报告日期 2024 年 09 月 25 日

Report Date Y M D

声 明 Introduction

1.报告无“CMA 资质认定章”和检测单位“检测专用章”及“骑缝章”无效。

This report no seal on the perforation and CMA qualification certification seal and special seal for testing is invalid.

2.报告无编制人、审核人、签发人签名无效，报告经涂改无效。

This report without prepare people signature, audit staff signature, approver signature is invalid, The report by alter is invalid.

3.报告未经本机构批准，不得复制（全文复制除外）本报告或证书。

This report or certificate can't be copied (except in full) without the approval of the agency .

4.对委托人送检的样品进行检测的，检测报告对样品所检项目的符合性情况负责，送样样品的代表性和真实性由委托人负责；除委托方特别声明并支付样品管理费以外，所有样品超过标准或技术规范要求的时效性均不再留样。

If the sample submitted by the client is tested, the test report shall be responsible for the conformity of the items tested by the sample, and the client shall be responsible for the representativeness and authenticity of the sample submitted; Unless the entrusting party makes a special statement and pays the sample management fee, the timeliness of all samples exceeding the requirements of standards or technical specifications will not be retained.

5.委托方应对提供的检测相关信息的完整性、真实性、准确性负责。本公司实施的所有检测行为以及提供的相关报告以委托方提供的信息为前提，当委托方提供的信息可能影响结果的有效性时，本公司不承担由此引起的任何责任。

The entrusting party shall be responsible for the completeness, authenticity and accuracy of the testing related information provided. All testing behaviors and related reports provided by our company are based on the information provided by the entrusting party. When the information provided by the entrusting party may affect the effectiveness of the results, our company will not assume any responsibilities arising therefrom.

6.报告未经检测单位同意不得用于广告，商品宣传等商业行为。

This report without the consent of the testing organization shall not be used for advertising, advertising products such as business practices.

7.委托方如对本检测报告有任何异议，请于收到报告之日起十五日内向本公司提出申请，逾期不申请的，视为认可本检测报告。

If the client has any objection to the test report, please apply to the company within 15 days from the date of receiving the report. If the client fails to apply within the time limit, it shall be deemed to have approved the test report.

地 址： 云南省昆明经济技术开发区云大西路 39 号新兴产业孵化区 3 幢 3 层厂房
Address: The 3-story factory Building, 3 Building, Emerging Industry Incubation Zone, No.39 Yunda West Road, Kunming Economic and Technological Development Zone, Yunnan Province.

邮 编： 650500

Postcode ID:

电 话： 0871-63852008

Telephone No:

传 真： 0871-63802005

Fax No:

网 址： www.sttynzk.com

Website:

1.企业生产情况

表 1 企业工况

生产工单编号	主要产品名称	实际生产能力	监测期间 生产能力	监测期间运行情况	运行负荷
YNZKSC 20240909001	医疗废物处理	2919.711 吨/年	9.092 吨/天	正常	93.4%



2.检测信息

表 2 检测信息

客户基本情况										
委托单位信息		单位名称	大理丰顺医疗废物处置有限公司							
		通讯地址	大理州大理市下关镇吊草村大风坝垃圾处理场以西							
		联系人	姚燮林	联系电话		13987202591				
受检单位信息		单位名称	大理丰顺医疗废物处置有限公司							
		通讯地址	大理州大理市下关镇吊草村大风坝垃圾处理场以西							
		联系人	姚燮林	联系电话		13987202591				
样品基本情况										
样品类别	样品名称	采样点位	采样频次		采样人员	采样时间	收样人员	收样时间	分析时间	样品状态描述
			天数	次/天						
水和废水	地下水	W2: 上游井 (E100°16'7.22", N25°31'19.10")	1	3	李光辉 段灵波	2024.09.14	张晓川	2024.09.15	2024.09.15- 2024.09.19	样品均为无颜色、无气 味、无浮油、无浑浊。
		W3: 下游井 (E100°16'5.04", N25°31'20.15")								样品均为微黄色、微弱 气味、无浮油、无浑浊。
		W4: 侧下游监测井 (E100°16'7.07", N25°31'22.37")								样品均为微黄色、无气 味、无浮油、无浑浊。
		W5: 内侧下游监测井 (E100°16'6.85", N25°31'20.45")								样品均为微黄色、无气 味、无浮油、无浑浊。

3.生产工单编号、检测类别、项目、方法、设备

表 3 检测分析方法及主要仪器设备一览表

生产工单编号	样品类别	检测项目	检测方法	检测和分析设备	仪器编号	分析人员	检出限/ 最低检测质 量浓度
YNZKSC 20240909001	水和废水	铅	水质 65 种元素的测定 电感耦合等离子体质谱法 HJ 700-2014	ICAP RQ ICP-MS	YNZK-FX149	许正兰	0.09µg/L



4.检测结果

表 4 地下水检测结果表

NO.1

检测点位		W2: 上游井				W3: 下游井			
采样时间 / 样品编号		2024.09.14							
检测项目 (单位)		YNZKSC 20240909001-W005	YNZKSC 20240909001-W006	YNZKSC 20240909001-W007	YNZKSC 20240909001-W011	YNZKSC 20240909001-W012	YNZKSC 20240909001-W013		
铅 (mg/L)		9.72×10 ⁻³	9.47×10 ⁻³	9.52×10 ⁻³	2.15×10 ⁻²	2.19×10 ⁻²	2.19×10 ⁻²		
备注		采样方式: 瞬时采样。							

NO.2

检测点位		W4: 侧下游监测井				W5: 内侧下游监测井			
采样时间 / 样品编号		2024.09.14							
检测项目 (单位)		YNZKSC 20240909001-W008	YNZKSC 20240909001-W009	YNZKSC 20240909001-W010	YNZKSC 20240909001-W014	YNZKSC 20240909001-W015	YNZKSC 20240909001-W016		
铅 (mg/L)		2.48×10 ⁻²	2.51×10 ⁻²	2.52×10 ⁻²	6.11×10 ⁻³	6.50×10 ⁻³	7.30×10 ⁻³		
备注		采样方式: 瞬时采样。							

报告结束

附图:

大理丰顺医疗废物处置有限公司 2024 年 9 月地下水自行监测点位图



1. 项目背景
2. 项目目标
3. 项目范围
4. 项目组织
5. 项目计划
6. 项目执行
7. 项目监控
8. 项目收尾

1. 项目背景

2. 项目目标